

消化ホース 通水テスト実施（令和3年1月21日：有田市消防本部）

消化ホース一覧

	No											
	1	2	3	4	5	6	7	8	9	10	11	12
2017												2
2016												
2015												1
2014												
2013												
2012												
2011												
2010												
2009												
2008												
2007												
2006												
2005												
2004												
2003												
2002												
2001												
2000												
1999												
1998												
1997												
1996												
1995						3						
1994												
1993												
1992												
1991												
1990												
1989												
1988												
1987												
1986												
1985												
1984												
1983						2	1	1				
1982					1							
1981												
1980								1				
1979												
1978	1											
1977												
1976	2				2							
1975								2	2			
1974												
1973						1		1				
1972							4					
1971												
1970												
不明	5	1	7	3			2	1	3			

評価：△（水漏れあり）



評価：×（水漏れ多：使用不可）



評価：△（水漏れあり）



ホース格納庫 No.1 12月7日



